General Environmental Incident Summary

Incident: 1355 Notice: 2/12/2011 0500 Occurred: 2/12/2011 0500

DEM Incident No: No Further Action:

Responsible Party: J5 Transport **County:** Burleigh

Twp Rng Sec Qtr: 138 80 8 NE

Lat Long + Method: 46.79393 -100.79510 Address matching

Location Description: Pony Express Conoco - 1020 South Washington Street, Bismarck, ND

701-223-3816

Submitted By Info: Ken Stoxen

Received By Info:

Contact Info: KEN STOXEN

101 Old Red Trail

Mandan ND 58554

Affected Medium: 03 - soil

Near. Occupied Bldg: 50 Feet

Type of Incident: Tank Overflow

Release Contained:

Reported to NRC: Unknown

Contaminant: 10% Alcohol and gasoline

Volume of Release: 50 gallons

Duration of Release: 1.75 hours

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0
Number of Injuries: 0

Cause of Incident:

ICE IN FILL HOLE DID NOT PERMIT A TIGHT FIT OF DROP FITTING AND FITTING POPPED OFF DUE TO ICE AROUND FITTING. GASOLINE THEN RAN INTO THE STREET

Risk Evaluation:

TEMPERTURE WAS +36 DEGREES CLEAN UP WAS ALMOST IMMEDIATE AND COMPLETE RISK WAS MINIMAL

Potential Env. Impacts:

SHOULD BE NONE

Action Taken/Planned:

THE SPILL KIT ON THE J5 TRUCK WAS USED TO CONTAIN SPILL. KEN STOXEN WAS CALLED AT 5:00 AM AFTER SPILL KIT WAS SET AND HE ADVISED CALLING THE BISMARCK FIRE DEPT..THE FIRE DEPT WAS IN FAVOR OF USING FLOOR DRY TO CLEANUP GASOLINE. KEN STOXEN AND MARK MILLER, DISPATCHER FOR J5 TRANSPORT, ARRIVED AT 5:45 WITH FLOOR DRY AND CLEANUP EQUIPMENT.BY 6:45 AM THE SPILL WAS CLEANED UP TO THE SATISFACTION OF MEL FISHER, ENVIROMENTAL HEALTH ADMINISTRTOR FOR THE BISMARCK FIRE DEPT. USED FLOOR DRY WAS TAKEN ON A PICKUP TO MISSOURI VALLEY PETROLEUMS SHOP. THE PICKUP WAS LEFT OUTSIDE TO AIR OUT AND KEN STOXEN WILL CALL THE HEALTH DEPT. MONDAY MORNING TO SEE ABOUT FARMING THE MATERIAL. PLANNED FUTURE ACTION WILL BE TO NOTIFY ALL DEALERS TO CLEAN SUMP HOLES OF

ALL ICE TO PREVENT UNLOADING EQUIPMENT FAILURE.

Wastes Disposal Location:

AS PER THE ND HEALTH DEPT

Other Agencies Involved:

NDDES, State Fire Marshal, Local Fire Department, Local Law Enforcement, Local Emergency Manager

Updates

Date: 10/1/2018 **Status:** Awaiting Documentation

Author: Martin, Russell

Notes:

Corrected lat/long, based on street address.

Updated Volume: None at the time of this update

Date: 10/2/2018 Status: Reviewed - No Action Required

Author: Martin, Russell

Notes:

Received incident report narrative conducted by Bismarck Fire Department. FD personnel noted that none of the gasoline made it into the storm sewer. Report contact no longer with the company. No further follow-up required at this time.

Updated Volume: None at the time of this update